

## **Field Note Record**

Contract No. Station		Mile/Line:	C/S	C/S			
009359	Section 4B CO #2 R1	US-12					
Staked by	Date	Work Started Date		Work Completed Date			
SURVEY		10/15/2019					
9/6/2019							
Calculated by	, Date	Checked by	Date	Inspector	Date		
Scott Busby		E. Knudson		Scott Busby	11/5/19		
11/5/2019		11/13/2019					

ITEM NO. 32
Section 4A - US-12, MP 192.85 to MP 202.65
Change Order # 3
CONTRACTOR STANDBY TIME

Est.#8

Lump Sum - 100% completion = \$1,825.00

**Material Brand** 

## **Group Number 29**

7/8/2019 -US-12

• Station MP 199.50 P1 N. 40TH Ave Off ramp MP 0.46

Manufacturer

• Post depth issue at culvert crossing

	Name/Model Type			Name/Model Type			Ref. No.	Code			
léa ma	Item Description	C	Data Wash	Unit	Quantity	Ledger Entry No.	De	ata d Du	Chashad Bu		Est. No.
ltem Num		Grp	Grp Date Work Complete					sted By Date	Checked By Init. Date		
0032	CO 3-CONTRACTOR STANDBY TIME	29	10/23/20	L.S.	1,825.00	335	EK	11/20/19			8

Brand

RAMS/QPL

Appr/Acc Basis of Accept

## **Attachments**



Item Num

FNR32 1557\_001.pdf Adobe Acrobat Document 13.2 KB

DOT Form IP 422-635ER EF Revised 4/2009